

Project Name: VA – Marion Assessment Project Number: 11-1300-0017
 Building Name: Building 8 Address: 1700 E. 38th Street, Marion IN 46953
 Sampled By: Linda Kelly Date: May 19, 2011

Sample Number	Material	HA #	Location	% Asbestos
MAR - 077A	1x1 Cream & Gray Streaks Floor Tile	01	Basement Room 1	ND
MAR - 078A	1x1 Cream & Gray Streaks Floor Tile	01	Room 5	ND
MAR - 077B	Mastic Associated with 1x1 Cream & Gray Streaks Floor Tile	02	Basement Room 1	2.7% Chrysotile
MAR - 078B	Mastic Associated with 1x1 Cream & Gray Streaks Floor Tile	02	Room 5	*
MAR - 079A	1x1 Light Gray, Black Streaks Floor Tile	03	Basement Room 3	*
MAR - 080A	1x1 Light Gray, Black Streaks Floor Tile	03	Basement Room 5	8.2% Chrysotile
MAR - 079B	Mastic Associated with 1x1 Light Gray, Black Streaks Floor Tile	04	Basement Room 3	*
MAR - 080B	Mastic Associated with 1x1 Light Gray, Black Streaks Floor Tile	04	Basement Room 5	10% Chrysotile
MAR - 081A	1x1 Gray Floor Tile	05	Basement Room 4	ND
MAR - 082A	1x1 Gray Floor Tile	05	Basement Room 4	ND
MAR - 081B	Mastic Associated with 1x1 Gray Floor Tile	06	Basement Room 4	1.2% Chrysotile
MAR - 082B	Mastic Associated with 1x1 Gray Floor Tile	06	Basement Room 4	*
MAR - 083A	1x1 Spotted Ceiling Tile	07	Basement	ND
MAR - 084A	1x1 Spotted Ceiling Tile	07	Basement	ND
MAR - 083B	Mastic Associated with 1x1 Spotted Ceiling Tile	08	Basement	1.3% Chrysotile
MAR - 084B	Mastic Associated with 1x1 Spotted Ceiling Tile	08	Basement	*
MAR - 085	Interior Window Glazing	09	1 st Floor - Room 9	ND
MAR - 086	Interior Window Glazing	09	Basement Room 2 (bathroom)	ND
MAR - 087	Interior Window Caulk	10	Basement Room 3	ND
MAR - 088	Interior Window Caulk	10	Basement Room 5	ND
MAR - 089	Exterior Window Caulk	11	Exterior Basement Windows	ND
MAR - 090	Exterior Window Caulk	11	Exterior Basement Windows	ND
MAR - 091	Exterior Window Glazing	12	Exterior Basement Windows	ND

*If first or any sample in a supplied group is positive, then all are assumed positive
 ND – No Asbestos Detected

Project Name: VA – Marion Assessment Project Number: 11-1300-0017
Building Name: Building 8 Address: 1700 E. 38th Street, Marion IN 46953
Sampled By: Linda Kelly Date: May 19, 2011

Sample Number	Material	HA #	Location	% Asbestos
MAR - 092	Exterior Window Glazing	12	Exterior Basement Windows	ND

Note: All Samples Positive for ACM are **Bolded**.

*If first or any sample in a supplied group is positive, then all are assumed positive
ND – No Asbestos Detected